Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Maintenance of toilet at J.P.Park in Ward NO.17 in RRN Zone
2	Administration Approval & Date	CE/RRN/AS/11/10-11 Dtd 23-04-2011 by CE (RRN)
3	Technical Sanction Estimate No. & Date	CE/RRNZ/TS/21/10-11 dtd:23-04-2011 by CE (RRN)
4	Estimate Amount	Rs.20.00/- Lakhs
5	Job Code No.	017-11-000042
6	P-Code	P-0974
7	Agreement No & date	EE(P)/RRN/AG No./18/2011-12 Dtd.04-05-2011
8	Work order Number & Date	EE/Proj/RRN/W.O/18/2011-12 Dtd.04-05-2011
9	Contract Amount as per Agreement	Estimated Amount +10%
10	Bill Amount	Rs.19,06,163/-
11	B.R. No. & Date	328/2012-13 dt.30-08-2013
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	516/ Pages 51519 to 51536
14	Date of Inspection	5/7/2015
15	Enclusures	1) Extract of MB No.516 Page No.51536 2) 4 Number of photos taken during inspection
16	Inspection Report	The above site was Inspected by adm with the concerned officials. The measurements was checked by me and found to satisfactory

As Pursuit letter received plz to submit pmnt

EE (P) RR Nagara

5/7/2015

(R.Sathyanarayana)
Inspection Report officer,

M.A.R. 57 (Rule 116)

Measurement Book

No. C/09

No. ..... From ..... To 051536 7

of work .....

of Contractor of nature of Agency .....

of commencement of work .....

Full description, etc, of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement	Reference to last Measurement
	3	4	5	6	7	8	8
Up Park Main Road → Main Gate Animal Statue 2 Nos. Ticket Counter Gate. Road. Rajkumar Statue Rock garden Pathway Pathway Toilet Work Spot Musical Fountain. Pathway Toilet Work Spot Bridge. Pathway Milky alongside Main Road. Gate Cp Area. ASE(P)-I RRN							Sanitary and above dressing in clear from plate as 80.00 M7.5 with tal coope I machine ted. in machinery

t:- 50.00 lacs

Tagore Zone

t:-

5/7/2018

Inspection Officer